

Mushroom Express

33777 Valley Center Rd
Valley Center, California



PHOTOGRAPH 1:

Sanitary wastewater from entire lot is plumbed to a septic system (*UIC 1a and 1b*). Former structures both had septic plumbing that extended from the west side of the building to Valley Center Road.



PHOTOGRAPH 2:

Waste oil pad contains two drums with minimal contents (waste oil). Does not present an immediate risk to health or the environment, but should be managed appropriately. Historical spills and usage warrants shallow subsurface investigation in the area.



PHOTOGRAPH 3:

Diesel storage tank was burned during the fire and the south wall of the tank 'blew' off. It is likely diesel was spilled on the south side of the tank, this area should be investigated

Mushroom Express
33777 Valley Center Rd
Valley Center, California



PHOTOGRAPH 4:

Drinking water well, Tribe is concerned that the well may act as a conduit for contaminants associated with the site into the underlying aquifer. The well should be sampled to determine if contamination is likely.



PHOTOGRAPH 5:

Cooling humidifier system (UIC 2) - drain



PHOTOGRAPH 6:

Cooling humidifier system (UIC 2) - sump

Mushroom Express
33777 Valley Center Rd
Valley Center, California



PHOTOGRAPH 7:

Cooling humidifier system (*UIC 2*) – watering area



PHOTOGRAPH 8:

Laundry water sumps (*UIC 3 and 4*) are located on the south side of the former south structure. Although this area was reportedly used for laundry water (grey water) for 2 – 4 weeks, it should be investigated.